



GLASS & CERAMICS

APPLICATION INSTRUCTIONS

WWW.DRYWIRED.COM



PRODUCT DESCRIPTION	This coating repels water and oil creating a self-cleaning surface for glass and ceramics without the use of harsh toxic cleaners.
SURFACE PREPARATION	Ensure a clean, dry surface before application – use isopropyl alcohol or ethyl alcohol to remove contaminants. A degreaser may be necessary for hard to clean or greasy surfaces. If there is prior staining, sand to remove stains before applying our coating. Our coating will not remove already present staining.
APPLICATION	Spray and wipe with a clean paper towel, or cloth- like a cleaning solution would be used. An industrial spray-coating system is also acceptable at the manufacturing level.
CURE TIME	This coating completely adheres to the surface after 24 hours of application. The coating will only exhibit the hydrophobic property after this curing period.
STORAGE	2 year unopened shelf life stored at -3°C to 30°C out of sunlight in a dry, well-ventilated area.
CONSUMPTION	5-15 ml/m ²
EXTENDED CARE & MAINTENANCE	Coating can withstand all cleaning solutions with a pH less than 11. Use residue and fragrance free cleaners. Recommended cleaners: Ethyl Alcohol, Isopropyl Alcohol